

IMPORTANT SAFETY RECALL

Dear Customer,

Date: July 29, 2015

This notice is sent to you in accordance with the National Highway Traffic and Motor Vehicle Safety Act.

Shandong Jinyu Industrial Co., LTD ("Jinyu") has decided that a defect which relates to motor vehicle safety may exist in certain Jinyu brand and Evergreen brand tires, in sizes LT225/75R16 10PR. Jinyu has initiated a tire safety recall to remove these tires from service. You have been identified as a potential owner of an affected tire.

Please read this notice carefully and follow the steps outlined in the instructions below.

Why is Jinyu taking this action?

Jinyu has determined that some of these tires may have a defect involving irregular geometry in the shoulder area which may lead to heat buildup and the formation of separation which may lead to eventual tire failure increasing the risk of a crash.

Affected Tires


The Jinyu and Evergreen LT225/75R16 10PR tires are identified as follows:

Product Line:	Jinyu LT225/75R16 10PR YS78
DOT TIN Range:	KEE5 AMJ 1611 thru KEE5 AMJ 4314
Product Line:	Evergreen LT225/75R16 10PRES89
DOT TIN Range:	KEE5 AMJ 1611 thru KEE5 AMJ 4314

The subject tires were sold as replacement tires between 2011 and 2014.

The tires can be identified by the DOT serial number, also known as the Tire Identification Number, or TIN, found on the sidewall of each tire.

[键入文字]

Example: DOT KEE5 AMJ 4612DOT KE E5 AMJ 46 12

If the date of manufacture is not present on the one side, it will be located on the opposite side of the tire.

What should you do?

If you have one of the covered tires, please visit your place of purchase at your earliest convenience for inspection. If the dealer determines your tires are eligible under this recall they will provide replacement at a value up to but not exceeding USD100.00 per tire plus applicable taxes to cover the cost of free tire replacement and mount the new tires for free.

Please bring this letter with you to the dealer, as it identifies that you may be eligible under this recall campaign.

What will Jinyu do for you?

If you have an affected tire in service on the date you receive this notice, Jinyu, through your dealer, will provide replacement at a value up to but not exceeding USD100.00 per tire plus applicable taxes to cover the cost of free tire replacement and mount the new tires for free.

If you have paid to have this recall condition corrected prior to this notice you may be eligible to receive reimbursement. If you are the lessor of this Vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

This campaign will expire 60 days from the date of this letter, so it is important that you act as soon as possible to determine whenever your tires are covered by this campaign. If you have any problems obtaining the needed replacement, please contact Jinyu recall service center [键入文字]

at:844-260-9994.

If after having attempted to take advantage of this recall you believe you have not been able to have your tire remedied without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E. Washington, D.C. 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We apologize for any inconvenience this safety recall may cause, but your safety is our first concern.

Sincerely



SHANDONG JINYU INDUSTRIAL CO., LTD

No. 9 Guangxing Road, Guangrao Economic Development Zone, Dongying, Shandong